



MSP 214 Release Notes

RGBlink Science &Technology Co.,Ltd			
File Name:	MSP 214 Release Notes	File type:	Release Notes
File Number:	RGB-TP-YH201807004	File Version:	V1.1

Version: 1.3

- **Problem Solved**

1. Solve LED display flicker issue when MSP 214 transmitter get power or signal interruption.