

Release Note

Firmware Version(S):

V1.34

Release Date:

20250626

Applicable Models:

MSP 405

Changes/Fixes/Enhancements Included:

- Modification
 - Resolved an issue where partial devices HDMI output flickering;

Notes:

(1) If there is no special requirement, the shipped equipment does not need to be updated;

(2) This release is applicable to hardware version V1.3 and devices with touch screen function (the device working mode is mainly based on menu settings).