



MSP 200PRO Release Notes

RGBlink Science &Technology Co.,Ltd			
File Name:	MSP 200PRO Release Notes	File type:	Release Notes
File Number:	RGB-TP-YH201712001	File Version:	V1.0

MSP 200PRO

Version: 1.61

● Update

1.Output format auto saved.

Last setting of output format will be saved automatically.

2.The function of OUTSET is added.

Enable The setting of output type, bit and color range.

3. GENLOCK Setting auto saved.

4. The setting of input source can be saved automatically.

Selected signal source will display immediately when reboot MSP 200PRO.

● Optimization

1.Update method.

1)MSP 200PRO is updated via TF card

2)Steps: Remove TF card > insert TF card into computer > Replace the whole software package or replace the “Update. PKG” program that under Firmware File.

2. The layout of EDID Setting.

3. The switch between HDMI and USB signal. Reduce the possibility of blank screen when switch signal.

4. Reduces the possibility of operation stuck.

5. Setting of USB source.

1) Reduce USB file reading stuck .

2) Increase USB reading speed.



3)The layout of USB play list.

- **Problem Solved**

1. Input & Output format error.
2. Monitor abnormal flashing .
3. DVI Output abnormal flashing.