

Release Notes

Firmware Version(S):

V1.3.24_3.90_2.18

Release Date:

5th August 2022

Applicable Models:

TAO 1pro

Changes/Fixes/Enhancements Included:

- *Optimization: Optimize img format package upgrade, and add the manual restart process after the upgrade is completed.*
 - V1.3.04_3.76_2.14 and earlier versions, need to upgrade v1.3.07_3.77_2.14_PATCH first to support img format package upgrade.
 - After upgrading the IMG format package, the ZIP format package upgrade is no longer supported.
 - **Please do not connect any input ports when upgrade, to avoid failure of HDMI input firmware upgrade.**
- *Optimization: Optimize YouTube streaming noise.*
- *Optimization: Optimize the streaming of BiliBili, And fix the problem that there is sound but no picture when viewing live broadcast on Windows Web.*
 - MAC end and IOS mobile ends need to be further optimized.
 - During streaming, if there is no picture displayed at the viewing end, please adjust the bit rate then stream again.
- *Optimization: Improve NDI code rate and key frames, improve picture quality, and optimize the problem of non synchronization of NDI encoding with small probability.*
 - It's preferred to use NDI tools to view the picture of NDI encoded output from TAO 1pro.
- *Optimization: Optimize the compatibility of some UVC cameras such as EH-1080P4S .*
 - If you use our RGB-20X-USB PTZ as the UVC signal source, please use PTZ USB2.0 output interface of the camera.